



980423


1.




2.





A





B





C





A







B



C



o16 111 004 4,0 x 15 mm	A B 2x
G23 121 110 SP40	A B 8x
121 115 SP40 4 x 40 mm	6x
SP27 4 x 27mm 122620	A 6x B 12x C 10x



1

121 115

SP40

4 X 40 mm

2

A

B

C

SP27

4 X 27mm

122620

3

G23

4,0 x 15 mm

111 004



980423


25.02.10 / 19.04.17










04 17

2 / 2

980446



	KS 1/2	1x
	H3	2x
111 106 4,0 x 15 mm	G23	4x
121 110		4x
122620	SP27	5x
4 X 27mm		




980446

16.02.11 / -



02 11

1/2

1



2



H3



111 106

4,0 x 15 mm


G23



121 110

SP27

4 x 27mm



122620

980446

16.02.11 / -

02 11

2/2