




MAX 30 Kg



MAX 3 Kg



DE

Montageanleitung

FR

Notice de montage

NL

Handleiding voor de montage

CZ

Montážní návod

HU

Szerelési útmutató

TR

Montaj talimatı

PT

Instruções de montagem

AR

تعليمات التجميع

GB

USA

Assembly instructions

IT

Istruzione di montaggio

PL

Instrukcja montażu

SK

Návod na montáž

RO





Instrucțiuni de montaj

RU

Инструкция по монтажу

ES

Instrucciones de montaje





Service • Dienstverlening • Serwis • Servis • Сервисная служба • Servizio

Name • Naam • Nazwa • İsim • Название • Nom • Nome

Nr. • No. • Номер • Nu.













Тур • Туре • Тір • Тип • Тіро



Code	Qt.	Dimensions	Box	Code	Qt.	Dimensions	Box
12	3	284x60x16	1-1	466	1	208x434x16	1-1
76	2	246x149x16	1-1	467	1	547x245x16	1-1
440	1	1450x60x16	1-1	501	1	250x382x16	1-1
459	1	208x414x16	1-1	502	1	250x382x16	1-1
461	1	1600x382x16	1-1	503	2	318x382x16	1-1
462	1	797x206x16	1-1	504	1	362x194x16	1-1
463	1	797x206x16	1-1	FI3603	2	332x240x3	1-1
464	1	1101x414x16	1-1	FI3897	1	1099x208x3	1-1
465	1	1101x434x16	1-1	FI3898	1	546x222x3	1-1
456	1	208x434x16	1-1	SP0734	1	519x400x4	1-1



12



2 x FE2637 N60-K6

