

DE

AT

CH

Montageanleitung

FR

CH

Notice de montage

IT

CH

Istruzioni di montaggio

NL

Montagehandleiding

PT

Instruções de montagem

EN

Assembly instruction

E

Instrucción de montaje



PL

Instrukcja montażu

HR

Upute za instalaciju


79458556



79458556


Step 1

The diagram shows a 3D perspective of a rectangular wall. A bracket is being mounted to the wall. A dashed line indicates the path of a screw being inserted into a pre-drilled hole in the wall. A label 'Wall' points to the surface. A callout 'A' points to a detailed view of the screw and the bracket's mounting arm.



Step 2

The diagram shows a 3D perspective of a rectangular panel. Two screws are shown being driven into the panel, indicated by dashed lines. A leader line points from the label 'B' to the bottom edge of the panel.



Step 3

The diagram shows a rectangular panel being mounted to a wall. A label 'Wall' points to the wall surface. A screw is shown being inserted into the panel, with a dashed line indicating its path through the panel and into the wall. A dimension line indicates a 5mm gap between the panel and the wall. A spirit level is placed against the bottom edge of the panel to ensure it is level.

